



Step-fix



Repairs to steps and pallets on site




Representing Step-fix in Scandinavia in cooperation with Mulder Montage.

EFFICIENT REPAIRS ON SITE WITH STEP-FIX

Mulder Montage has developed a method for repairing worn ribs on the standing areas of escalator steps and moving walk pallets. This patented method is based on repairing damage using a filler material, returning the worn rib to its original form. In Scandinavia the step-fix is performed by Nordic Installation that are located in Sweden.

NO MORE UNDESIRED SHUT-DOWNS

Until now, repairs to ribs have either made use of welding techniques, or by replacing an entire step. Both these solutions are expensive, labour-intensive, harmful to the environment (CO₂ emissions), and require an undesirable shut-down of the installation. Step-fix offers a suitable solution.



Before

After

Benefits of Step-fix:

- Lowers maintenance costs
- Repairs on site
- Reduced shut-down during repairs
- Less harmful to the environment (reduced CO₂-emissions)
- Increased safety
- Certified repair method
- Patented process

RIB REPAIRS

According to NEN-EN115 standards, the ribs on the standing areas of escalator steps and moving walk pallets must comply with requirements for minimal dimensions. This is in the interests of safety for the users. Various external factors (such as stones trapped between comb plates) can cause damage to the ribs and pallets, so that they no longer meet the dimensional requirements. Damage will be detected during periodic inspections and must be rectified before the installation can be approved under NEN-EN115 standards.

FOR MORE INFORMATION

Nordic Installation
Löddeköpinge AB
Kumlevägen 9, 246 32
Löddeköpinge, Sweden

Patrik +46(0)702 12 80 69
Anders +46(0)735 12 36 45

paka@nordicinstallation.se
ansv@nordicinstallation.se
www.nordicinstallation.se

